



ନିର୍ବାହୀ ଯନ୍ତ୍ରୀ କାର୍ଯ୍ୟାଳୟ ଜନସ୍ୱାସ୍ଥ୍ୟ ବିଭାଜନ,
ରାଉରକେଲା

OFFICE OF THE EXECUTIVE ENGINEER, P.H. DIVISION, ROURKELA

Email ID: - eephrkl@nic.in, Phone No:-0661-2664791

No. 1092 / date. 11.02.2021

To

The Principal,
Chinmaya Public School, Mohini Vihar,
Fertilizer- IDL Road, Rourkela-16.

Sub: Inspection report of Chinmaya Public School, Fertilizer, Rourkela-16.

Ref: Your Lr. No. CPS/612/2021 dt. 08.01.2021.

Sir,

I am enclosing herewith the inspection report regarding Sanitation & Drinking water condition Certificate in favour of " Chinmaya Public School, Mohini Vihar, Fertilizer-IDL road, Rourkela-16 for information & necessary action.

//Encl: Format-1 set.(2 Pages)

Yours faithfully,

MemomNo. 1093 / Dt. 11/2/21

Executive Engineer, (PH)

Copy to the Asst. Executive Engineer, P.H. Sub-Division Rourkela for information & necessary action with reference to his Lr. No.3690 dt. 08.02.21.

Executive Engineer, (PH)

MANAGER
CHINMAYA PUBLIC SCHOOL

Principal
CHINMAYA PUBLIC SCHOOL
UDISE Code - 21052005452

INSPECTION NOTE OF SRI ANUP KUMAR PATEL, EXECUTIVE ENGINEER,

P.H.DIVISION, ROURKELA.

1. Name of the School : Chinmaya Public School, Mohini Vihar,
Fertilizer-IDL road, Rourkela-769016
2. Year : 2020-21
3. Date of inspection : DT 01.02.2021
4. Name of the inspecting officer : Sridhar Pattnaik, Asst. Engineer, PHED, Rourkela
5. Date of previous inspection
& by whom made : Maheswar Pradhan, AEE & Sridhar Pattnaik; AE
PHED, Rourkela
6. Where the compliance report
on the previous inspection has
been submitted or not? : Not done
7. Whether defects pointed out in the
previous inspection note have been
rectified, if not why? : Yes
8. Strength of the School
 - a) Students : 600 Nos
 - b) Teaching Staffs : 30 Nos
 - c) Non-teaching Staffs : 10 Nos
9. Drinking water facilities
for the School building.
 - a) Source of water supply to
the School building. : Own (under ground water by tube well
and pumping arrangement) = 2sets
 - b) Storage capacity of the ground
reservoir inside the School building : Nil
 - c) Storage capacity of the ground
reservoir outside the School building : Nil
 - d) Storage capacity of the OHT
inside the School building : 23000 Ltr (Aprox)
 - e) Storage capacity of the OHT
outside the School building : Nil
 - f) How many taps are there
in side the School building? : 30 Taps
 - g) How many taps are there
outside the School building? : Nil
 - h) How many water cooler and purifier
are there inside the School building? : 05 Nos Purifiers
 - i) How many water cooler and purifier
are there outside the School building? : Nil
 - j) Are they adequate according to the
strength of the School? : Manageable



MANAGER
CHINMAYA PUBLIC SCHOOL



Principal
CHINMAYA PUBLIC SCHOOL
UDISE Code - 21052005452


10. Sanitary facilities inside the School building
- a) How many urinals are there in side the School building? : For Ladies - 10 Nos
For Gents - 25 Nos
- b) How many latrines are there in side the School building? : For Ladies - 9 Nos
For Gents - 12 Nos
- c) Are they adequate according to the capacity of the School? : Manageable
11. Are they cleaned daily with phenyl & naphthalene? : Appears to be cleaned on the date of inspection.
12. Have the exhaust fans been provided in the latrine? : No
13. Are there provisions of prohibition of smoking and spitting rules strictly followed? : School guideline to be followed.

GENERAL INSTRUCTION:-

1. Daily cleaning of toilets to be ensured.
2. Broken urinals, pans and wash basins to be replaced.
3. Make provision for more urinals & Latrines.
4. Flushing arrangements to be operational in toilets.
5. Provision for more drinking water facilities such as water taps outside and inside of the school campus to be ensured.
6. Provision for more washing basins to be ensured.
7. "No smoking" & "No Spitting" boards are to be provided
8. Exhaust fans to be installed in the latrine.
9. All the damaged toilets, urinals and latrines rooms to be well furnished with glazed tiles.
10. All the water reservoir tanks at all the floors should be cleaned frequently.


Assistant Engineer
P.H.section-I, Rourkela


Assistant Executive Engineer
P.H.Sub-Division Rourkela


Executive Engineer
P.H.Division, Rourkela


MANAGER
CHINMAYA PUBLIC SCHOOL


Principal
CHINMAYA PUBLIC SCHOOL
UDISE Code - 21052005452

11.2.21